

# CD Practice Test Questions and Answers

## 1. What does GD&T stand for in drafting?

- A) General Drafting & Tolerances
- B) Geometric Dimensioning & Tolerancing
- C) Graphic Detailing & Tolerances
- D) Geometric Design & Templates

## 2. Why is datum referencing important in GD&T?

- A) To make drawings more complicated
- B) To provide a reference for measurements
- C) To replace dimensioning entirely
- D) To increase tolerance levels arbitrarily

## 3. On a drawing, the note 'ASTM A36' refers to:

- A) A structural carbon steel specification
- B) An aluminum alloy designation
- C) A stainless steel grade
- D) A plastics material standard

## 4. Why is scale important in blueprint reading?

- A) To add aesthetic appeal to drawings
- B) To represent dimensions accurately
- C) To eliminate measurement requirements
- D) To create freehand sketches

**Answers: 1-B 2-B 3-A 4-B**

For More CD Questions and Answers FREE, CD Online Prep Training,  
CD Exam, CD Study Guide, CD Flashcards, CD Quizzes visit:

## CD Practice Test