

Certified Quality Inspector Practice Test Questions and Answers

1. What is the primary goal of quality inspection in manufacturing?

- A) To increase production speed
- B) To ensure products meet specified standards and requirements
- C) To reduce labor costs
- D) To eliminate all manufacturing processes

2. Which statistical tool is commonly used in quality control to monitor process variation?

- A) Pie charts
- B) Control charts
- C) Bar graphs
- D) Line graphs

3. What does "Six Sigma" represent in quality management?

- A) Six inspection steps
- B) A methodology for process improvement and defect reduction
- C) Six quality inspectors
- D) Six manufacturing stages

4. When should corrective action be taken in quality inspection?

- A) Only at the end of production
- B) When defects or non-conformances are identified
- C) Never during production
- D) Only when customers complain

Answers: 1-B 2-B 3-B 4-B

For More Certified Quality Inspector Questions and Answers FREE, Certified Quality Inspector Online Prep Training, Certified Quality Inspector Exam, Certified Quality Inspector Study Guide, Certified Quality Inspector Flashcards, Certified Quality Inspector Quizzes visit:

Certified Quality Inspector Practice Test

Practice Test Geeks © All Rights Reserved