

EPA 608 609 Practice Test Questions and Answers

1. What is the impedance symbol?

- A) P
- B) R
- C) I
- D) Z

2. Equipment for recovery must be:

- A) Used on all equipment manufactured after November 15, 1995.
- B) Used on all equipment manufactured after July 1, 1995.
- C) CSA approved.
- D) Certified by an EPA-approved testing laboratory.

3. The disposable cylinders must be:

- A) Recovered and used again.
- B) Used for air.
- C) Discarded.
- D) Stored away.

4. What is the use of soap bubble testing?

- A) to detect water leaks
- B) to pinpoint leaks
- C) to see if the condenser or evaporator is dirty
- D) only with CFCs and HCFCs

Answers: 1-D 2-D 3-C 4-B

For More EPA 608 609 Questions and Answers FREE, EPA 608 609 Online Prep Training, EPA 608 609 Exam, EPA 608 609 Study Guide, EPA 608 609 Flashcards, EPA 608 609 Quizzes visit: [EPA 608 609 Practice Test](#)